


Fig. 1



MX = Master of piconet x

- 1 ● BT unit, master
- 2 ○ BT unit, slave

4

- BT unit, master in one piconet, slave in one
- BT unit, slave in two piconets

5

- BT unit, master in one piconet, slave in two
- BT unit, slave in three piconets

6

Fig. 2



Fig. 3




Fig. 4




Fig. 5




Fig. 6





Fig. 7








Fig. 9